

Environmental Inspection Dynamics LLC
Mr. Kevin Cuyler
176 Arbor Ridge Dr.
Montgomery, IL 60538 USA
(630) 220-3362



Eurofins EMLab P&K

www.MoldREPORT.com

info@MoldREPORT.com

Approved by:

A handwritten signature in black ink, appearing to read 'Dr. Kamash Pillai', is written over a horizontal line.

Cluster Leader
Dr. Kamash Pillai

Dates of Analysis:
MoldReport Spore trap: 07-17-2023

Service SOPs:
MoldReport Spore trap (EM-MY-S-1038)†

†AIHA-LAP, LLC accredited service, Lab ID #176641

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the samples as received and tested. Information supplied by the client which can affect the validity of results: sample air volume.

Eurofins EPK Built Environment Testing, LLC ("the Company") shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

Client: Environmental Inspection Dynamics LLC

Contact: Mr. Kevin Cuyler
Project: Stactorek 71523-AT-1
Date of Sampling: 07-15-2023
Date of Receipt: 07-17-2023
Date of Report: 07-18-2023

MoldREPORT

Eurofins EMLab P & K
1815 West Diehl Road, Suite 800, Naperville, IL 60563
(866) 871-1984 Fax (856) 334-1040





Summary of Sample Analysis Results

Do not take any action based on the results of this report until you have read the entire report.

Air Sample Summary:

The MoldSCORE™ was in the LOW range for the following area(s): 35214396, 35214412. A low MoldSCORE™ indicates the air sample did not detect, relative to the outside air, the presence of indoor mold growth in this room at the time of sampling.

Please see the sections titled "Detailed Results of the Air Sample Analysis" and "Understanding Your Air Sample Analysis Results" for important additional information.

Location	MoldSCORE™				Exposure Level			
	Lower <110	200	Higher 300	Mold Score	Lower <200	1K	10K	Higher >70K
35214396: Front Bedroom * see p. 4 for details				123				
								Location spores/m3
								410
								Outside spores/m3
								4,500
35214412: Basement * see p. 5 for details				123				
								Location spores/m3
								450
								Outside spores/m3
								4,500